PRINTED: 06/08/2012 FORM APPROVED

(X3) DATE SURVEY STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION COMPLETED AND PLAN OF CORRECTION **IDENTIFICATION NUMBER:** A. BUILDING B. WING UT000535 06/04/2012 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 160 S 1000 E #120 **METRO HEALTH CENTER** SALT LAKE CITY, UT 84102 PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES (X5) COMPLETE (X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE PREFIX **PREFIX** DATE CROSS-REFERENCED TO THE APPROPRIATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) R432-600-25(4) G1920 G1920 R432-600-25(4) Maintenance Services (4) All buildings, fixtures, equipment and spaces Director of It will replace the 2 ceiling tiles in the communications room.

This was completed by Fred Pennington, Director of It on 4/5/12 shall be maintained in operable conditions. This STANDARD is not met as evidenced by: THIS IS A CLASS II DEFICIENCY. Based on a facility walk through with the administrator, the facility did not meet the requirements of this statute. Findings include: The facility's communications room did not have two ceiling tiles firmly secured in place. This situation compromised the fire integrity of the Utah Department of Health room (2009 IFC 315.2.4). JUN 1 9 2012 Bureau or treatm racing, Electronics. Certification and Resident Assessment Your Agency Name Mex 12 6/13/12 TITLE VO (X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

avies

Utah Department of Health STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER SUPPLIER CLIA IDENTIFICATION NUMBER: (X2) MULTIPLE CONSTRUCTION A. BUILDING: _

(X3) DATE SURVEY COMPLETED

UT000535

B. WING

10/03/2013

NAME OF PROVIDER OR SUPPLIER METRO HEALTH CENTER		STREET AD	STREET ADDRESS, CITY, STATE, ZIP CODE				
		160 S 1000 E SUITE #120 SALT LAKE CITY, UT 84102					
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIE (EACH DEFICIENCY MUST BE PRECEDE REGULATORY OR LSC IDENTIFYING INF	ED BY FULL	ID PREFIX TAG	PROVIDER'S PLAN OF C (EACH CORRECTIVE ACTI CROSS-REFERENCED TO TI DEFICIENCY	ON SHOULD BE HE APPROPRIATE	(X5) COMPLETE DATE	
	R432-600-26(3) Emergency Electrical (3) There shall be provision for emelighting according to NFPA 101. This STANDARD is not met as evidential in the part of a power facility manager on 10/02/13, the factorial provide emergency exit lighting at a areas. Findings: 1. The east exit stainwell that serve two required paths of egress from the was observed to not have a battery emergency light to illuminate the stainwell winds a power facility include evening hours on Monday winds a power facility from the stainwell winds illuminate the path of egress as required paths of egress as required paths of egress as required paths.	c Service ergency exit denced by: with the cility did not all required es as one of the clinic area back-up airwell in the anager, she y operation when the ow would not uired.	G2015	will install batter emergency light exit stairwell. be check in the chief acility check in Point person was responsible to emergency lights emergency lights exit stair well. East emergency	ery back-up in éast y Nov 20,2011 ck monthly gency st. will be check all in east light will	3	
		į		be added to mon emergency facil	thy ity checklist	11-20-	

Your Agency Name
LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

Veronica Galindo Clinic Managaca.

(X6) DATE

STATE FORM

If continuation sheet 1 of