AND PLAN OF CORRECTION IDENTIFICATION		(X1) PROVIDER/SUPPLIER IDENTIFICATION NUM	nen l'	LIA (X2) MULTIPLE CONSTRUCTION A. BUILDING:  B. WING			(X3) DATE SURVEY COMPLETED R 05/23/2013	
		AC13950034	B. WIN					
NAME OF PROVIDER OR SUPPLIER			STREET ADDRESS, O					
WOMA	AN'S CHOICE, INC.		18400 NW 75 PL HIALEAH, FL 33					
(X4) ID PREFIX TAG	(EACH DEFICIENC)	TEMENT OF DEFICIENCIES Y MUST BE PRECEDED BY F SC IDENTIFYING INFORMAT	ULL PREF ION) TAC	IX (EACH C	DER'S PLAN OF CORRECT CORRECTIVE ACTION SHOU EFERENCED TO THE APPRO DEFICIENCY)	JLD BE	(XS) COMPL DATI	
{A 000}	23, 2013 to the Sta was completed on on an acceptable p	view was conducted of the Licensure survey, w September 26, 2011. It lan of correction, the ed on the survey were	hich Based					

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

(X6) DATE

STATE FORM

TITLE

(Y5) Date

## State Form: Revisit Report

(Y1)	Provider / Supplier / CLIA / Identification Number AC13950034	(Y2) Multiple Construction A. Building B. Wing		(Y3) Date of Revisit 5/23/2013	
Name of Facility			Street Address, City, State, Zip Code		
A WOMAN'S CHOICE, INC.			18400 NW 75 PL SUITE #118 HIALEAH, FL 33015		

This report is completed by a State surveyor to show those deficiencies previously reported that have been corrected and the date such corrective action was accomplished. Each deficiency should be tally identified using either the regulation or LSC provision number and the identification prefix code previously shown on the State Survey Report (prefix codes shown to the left of each requirement on the survey report form).

(Y5) Date

(Y4) Item

(Y4) Item

(Y5) Date

(Y4) Item

ID Prefix Reg. # LSC		Correction Completed 05/23/2013	ID Prefix Reg. # LSC	A0600	Correction Completed 05/23/2013	ID Prefix Reg. #	Correction Completed
ID Prefix Reg. # LSC		Correction Completed	ID Prefix Reg. # LSC			ID Prefix Reg. # LSC	
ID Prefix Reg. # LSC		Correction Completed	D #		i	ID Prefix  Reg. #  LSC	Correction Completed
Reg #		Correction Completed	ID Prefix Reg. # LSC			Dog #	Correction Completed
ID Prefix Reg. # LSC		Correction Completed	ID Prefix Reg. # LSC			Pag #	Correction Completed
Reviewed By State Agenc Reviewed By	у	Reviewed By	Date:		of Surveyor:	rlp	Date: 5/23/13
CMS RO Followup to Survey Completed on: 9/26/2011 STATE FORM: REVISIT REPORT (5/99)				Check for any Uncorrected	Uncorrected Deficier Deficiencies (CMS-2	ncies. Was a Summary 1567) Sent to the Facili Event ID	r of ty? YES NO



RICK SCOTT GOVERNOR ELIZABETH DUDEK SECRETARY

May 23, 2013

Administrator A Woman's Choice, Inc. 18400 Nw 75 Pl Suite #118 Hialeah, FL 33015

Dear Administrator:

This letter reports the findings of a follow-up desk review that was conducted on May 23, 2013 to the State Licensure survey, which was completed on September 26, 2011.

Attached is the provider's copy of the State (3020) Form and Revisit Report. Based on an acceptable plan of correction, the deficiencies identified on the survey were determined to be corrected.

The Quality Assurance Questionnaire has long been employed to obtain your feedback following survey activity. This form has been placed on the Agency's website at <a href="http://ahca.myflorida.com/Publications/Forms.shtml">http://ahca.myflorida.com/Publications/Forms.shtml</a> as a first step in providing a web-based interactive consumer satisfaction survey system. You may access the questionnaire through the link under Health Facilities and Providers on this page. Your feedback is encouraged and valued, as our goal is to ensure the professional and consistent application of the survey process.

Thank you for the assistance provided to the surveyor. Should you have any questions please call Faith Randolph, Registered Nurse Consultant at (305) 593-3100.

Sincerely

Arlene Mayo-Davis

Field Office Manager, Area 11

Enclosures: State (3020) Form and Revisit Report