



Occupational Safety and Health Administration

Menu

- OSHA ▾
- STANDARDS ▾
- TOPICS ▾
- HELP AND RESOURCES ▾
- Contact Us
- FAQ
- A to Z Index
- English
- Español

Inspection Detail

Inspection: 316725167 - Planned Parenthood Mar Monte Response Center

Inspection Information - Office: Ca Fresno				
Nr: 316725167	Report ID: 0950625	Open Date: 09/05/2013		
Planned Parenthood Mar Monte Response Center				
90 W. Ashlan		Union Status: NonUnion		
Clovis, CA 93612				
SIC: 7389/Business Services, Not Elsewhere Classified				
NAICS: 561422/Telemarketing Bureaus				
Inspection Type:	Accident			
Scope:	Partial	Advanced Notice:	N	
Ownership:	Private			
Safety/Health:	Health	Close Conference:	04/07/2014	
		Close Case:	04/16/2014	
Related Activity:	Type	ID	Safety	Health
	Accident	101490332		

Accident Investigation Summary			
Summary Nr: 201498532	Event: 09/03/2013	Employees Suffers Face And Lung Exposure To Carbon Monoxide	
<p>On September 3, 2013, Employee #'s 1, 2, 3, 4, 5, and 6 were remodeling portions of a building interior to accommodate a new tenant. The project required relocating and abandoning septic lines in the slab foundation. The employees cut approximately 45 ft of concrete using a Husqvarna K-750 2-stroke gasoline powered quick cut saw equipped with water spray for silica dust suppression to prosecute the cutting. Between 9:00 - 9:30 a.m. the employees were complaining of odors, a haze in the lobby and were experiencing eye irritation, headaches, nausea, blurred vision, coughing and vomiting. Conditions worsened and a coworker called the DOSH in Fresno, and was informed they may have exposure to carbon monoxide (CO). The Clovis Fire Department was contacted for assistance to test the air for CO. The Clovis Fire Department evacuated the building and begins triage and treatment for CO exposure. After approximately two hours post arrival CO concentration was measured using a Draeger 4-Gas meter: less than or equal to 5 ppm in PP work area; 8 ppm in the common areas and construction area; 21 ppm highest reading in the construction area. Employees #1, 2, 3, 4, 5, and 6 were transported to two Acute Care hospitals, where they were treated for the exhaust fume containing CO exposure to their face, and lungs. The employees were later released.</p>			
<p>Keywords: eye, lung, building, headache, nose, saw, gasoline, carbon monoxide, cough, vomit</p>			
Inspection	Degree	Nature	Occupation
1 316725167	Non Hospitalized injury	Poisoning(Systemic)	Information clerks, n.e.c.
2 316725167	Non Hospitalized injury	Poisoning(Systemic)	Information clerks, n.e.c.
3 316725167	Non Hospitalized injury	Poisoning(Systemic)	Information clerks, n.e.c.
4 316725167	Non Hospitalized injury	Poisoning(Systemic)	Information clerks, n.e.c.
5 316725167	Non Hospitalized injury	Poisoning(Systemic)	Information clerks, n.e.c.
6 316725167	Non Hospitalized injury	Poisoning(Systemic)	Information clerks, n.e.c.

UNITED STATES
DEPARTMENT OF LABOR

Occupational Safety and Health Administration
200 Constitution Ave NW
Washington, DC 20210
☎ 800-321-6742 (OSHA)
TTY
www.OSHA.gov

FEDERAL GOVERNMENT

[White House](#)
[Severe Storm and Flood Recovery Assistance](#)
[Disaster Recovery Assistance](#)
[DisasterAssistance.gov](#)
[USA.gov](#)
[No Fear Act Data](#)
[U.S. Office of Special Counsel](#)

OCCUPATIONAL SAFETY AND HEALTH

[Frequently Asked Questions](#)
[A - Z Index](#)
[Freedom of Information Act](#)
[Read the OSHA Newsletter](#)
[Subscribe to the OSHA Newsletter](#)
[OSHA Publications](#)
[Office of Inspector General](#)

ABOUT THE SITE

[Freedom of Information Act](#)
[Privacy & Security Statement](#)
[Disclaimers](#)
[Important Website Notices](#)
[Plug-Ins Used by DOL](#)
[Accessibility Statement](#)